OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :BMW of North America, LLCSubmission Date :AUG 14, 2019NHTSA Recall No. :19V-601Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : BMW of North America, LLC Address : P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

Vehicle Information :

Vehicle 1:	2019-2019 BMW X1 s	Drive28i, X1 xDrive28i	
Vehicle Type :	LIGHT VEHICLES		
Body Style :	SUV		
Power Train :	GAS		
Descriptive Information :	Approximately 16 veh assembled according	nicles contain a steering gear tie to specifications.	rod end that may not have been
	to identify the start an	e assembly information to deter	d steering gears which was then
		erence to non-recall component ar tie rod end that may not have	
Production Dates :	MAR 15, 2019 - APR 0	5, 2019	
VIN Range 1:		End: NR	☐ Not sequential
C C	Begin : NR		☐ Not sequential
Vehicle 2:	Begin : NR 2019-2019 BMW X2 x		Not sequential
Vehicle 2 : Vehicle Type :	Begin : NR 2019-2019 BMW X2 x LIGHT VEHICLES		☐ Not sequential
Vehicle 2 : Vehicle Type : Body Style :	Begin : NR 2019-2019 BMW X2 x LIGHT VEHICLES SUV		☐ Not sequential
Vehicle 2 : Vehicle Type :	Begin : NR 2019-2019 BMW X2 x LIGHT VEHICLES SUV		☐ Not sequential
Vehicle 2 : Vehicle Type : Body Style : Power Train :	Begin : NR 2019-2019 BMW X2 x LIGHT VEHICLES SUV GAS	Drive28i cle contains a steering gear tie ro	



19V-601

P

Population :

Number of potentially involved :32Estimated percentage with defect :100 %

art 573 Safet	y Recall Report	19V-601 Pag
	Recall component difference to non-reca contains a steering gear tie rod end that specifications.	
Production Dates : VIN Range 1 :	MAR 13, 2019 - MAR 13, 2019 Begin : NR End : N	NR 🗌 Not sequentia
Vehicle Type : Body Style : Power Train :	GAS Approximately 1 vehicle contains a steer assembled according to specifications. Basis for recall population determination to identify the start and end date of poter	
Production Dates : VIN Range 1 :	MAR 18, 2019 - MAR 18, 2019 Begin : NR End : M	NR 🗌 Not sequentia
Vehicle Type : Body Style : Power Train :	GAS Approximately 3 vehicles may have been steering gear tie rod end that may not ha specifications. Basis for recall population determination to identify the start and end date of poten	n equipped during a service visit with a ave been assembled according to n: Supplier production information was us ntially affected steering gears which was th aformation to determine the start date and eles. Il component: The recall component

Part 573 Safety Recall Report

19V-601

Page 3

Production Dates :	UL 28, 2017 - NOV	/ 25, 2017		
VIN Range 1: B	egin : N	NR E	nd: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train : Descriptive Information :	LIGHT VEHICLES SUV GAS Approximately 11 assembled accordi Basis for recall pop to identify the star	vehicles contain ing to specification pulation determ t and end date of	n a steering gea ons. ination: Suppli of potentially af	per Works Countryman r tie rod end that may not have been er production information was used fected steering gears which was then determine the start date and the end
Production Dates :	contains a steering specifications. MAR 15, 2019 - AP	difference to no g gear tie rod en R 08, 2019	n-recall compo d that may not i	nent: The recall component have been produced to
VIN Range 1 : B	egin : N	NR E	nd: NR	☐ Not sequential
Description of Defect :				
Description of the Defec	supplier, the st specifications. spherical wash	eering gear tie r Specifically, it n	od end may no nay not have be his could lead to	During production at the sub- t have been produced to een assembled with a required o excessive wear of the tie rod
FMVSS 1				
FMVSS 2		oka this would	lead to a loss of	f wheel guidance, increasing the
Description of the safety MSP	. If the nerou bi	one, uns would	10au 10 a 1055 0	i wheel guiuance, incieasing the

risk of a crash. Description of the Cause : NR

Identification of Any Warning NR that can Occur :

Supplier Identification :

Component Manufacturer

Name : Nexteer Automotive

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

19V-601

Address : Wilhelm-Wagenfeld Str. 28 Munich FOREIGN STATES 80807 Country : Germany

Chronology :

In early April, during the axle subassembly process at a vehicle assembly plant, a missing spherical washer was noticed when removing a plastic cap from the steering tie rod end. An inspection of 7,045 steering gears before assembly was performed which resulted in the identification of 3 additional suspect components.

A test program and engineering review was initiated to assess the durability of a tie rod end without the spherical washer. Suspect parts were tested to simulate and assess vehicle service life endurance.

In April and May, a review of the supplier's and sub-supplier's production processes was conducted. The supplier's and sub-supplier's production records involving tightening torques and torque curves of the tie rod assembly process were reviewed.

In early June, this review pointed to possible process fault in the monitoring system of the tie rod end assembly station during a specific production period. Further reviews enabled identification of the suspect tie rod serial numbers and associated production dates.

In early July, the results of the durability test program indicated that, over the service life of the vehicle, the tie rod could be subject to excessive wear and eventually break.

Vehicle manufacturing and Tier-1/Tier-2 supplier production records were examined in order to determine the number, and production dates, of potentially affected vehicles.

On August 7, 2019, BMW decided to conduct a voluntary recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Description of Remedy :

Description of Remedy Program :	The steering gear tie rods will be inspected and, if necessary, affected tie rods and ball joints will be replaced.
	Owners will be notified by First Class mail and instructed to take their vehicle to an authorized BMW center to have the remedy performed for free. If this condition were to occur to a potentially affected vehicle prior to the recall, the remedy would be covered by the BMW New Vehicle Limited Warranty program. Therefore, reimbursement for a pre- notification remedy re Part 573.13 and Part 577.11 is not necessary.
The information	contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

How Remedy Component Differs from Recalled Component :	Part numbers are as follows: X1 –tie rod (left/right): 31 21 6 876 645/646 // ball joint (left/right): 32 10 6 869 424/425 X2 – tie rod (left/right): 31 21 6 876 853/854 // ball joint (left/right): same as X1 Cooper Convertible – tie rod (left/right): 32 21 6 876 643/644 // ball joint (left/right): 32 10 6 854 734/737 Cooper Countryman – tie rod (left/right): 32 21 6 876 645/646 // ball joint (left/right): 32 10 6 869 424/425
Identify How/When Recall Condition was Corrected in Production :	NR
Recall Schedule :	
Description of Recall Schedule :	Notification to dealers is expected to begin and end on August 14, 2019. Notification to owners is expected to begin and end on October 7, 2019.

Planned Dealer Notification Date :	AUG 14, 2019 - AUG 14, 2019
Planned Owner Notification Date :	OCT 07, 2019 ⁻ OCT 07, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573