#### OMB Control No.: 2127-0004

76

## **Part 573 Safety Recall Report**

Manufacturer Name : BMW of North America, LLC Submission Date : JUN 17, 2020 NHTSA Recall No.: 20V-283 Manufacturer Recall No.: NR

### **Manufacturer Information :**

Manufacturer Name: BMW of North America, LLC Address: P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

## **Vehicle Information :**

Vehicle 1:	2020-2020 BMW X1 xDriv	ve28i, X1 sDrive28i	
Vehicle Type :	LIGHT VEHICLES		
Body Style :	SUV		
Power Train :	GAS		
Descriptive Information :		s are equipped with an air bay y not have been produced to s	
	records were reviewed to (May 16, 2016 and May 30 potentially affected vehicl	determine the production ra 0, 2016) and, via parts tracea es.	mbly and supplier production nge of potentially suspect parts bility, the production range of
		nce to non-recall component: which may not have been pr	
Production Dates :	MAR 18, 2020 - MAR 19, 2	2020	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved :

Estimated percentage with defect : 1%

**Population :** 

## 20V-283

20V-283

Page 2

Vehicle 2 : Vehicle Type : Body Style : Power Train :	LIGHT VEHIC 4-DOOR		ve28i, X2 sDrive28i	
Descriptive Information :	rollover sens	sor which ma	y not have been produced t	ag control unit containing a o supplier specifications. sembly and supplier production
	(May 16, 201 potentially a	6 and May 3 ffected vehicl	0, 2016) and, via parts trace es.	range of potentially suspect part eability, the production range of
	-	llover sensor	nce to non-recall componen which may not have been	5
Production Dates : VIN Range 1 :		0 - MAR 19, 2 NR	2020 End: NR	□ Not sequential
Vehicle 3 : Vehicle Type : Body Style : Power Train :	LIGHT VEHIO 2-DOOR	-	2 Door (Cooper, Cooper S, .	John Cooper Works)
Descriptive Information :	Basis for recarecords were	sor which ma all population e reviewed to	y not have been produced t n determination: Vehicle as determine the production	sembly and supplier production range of potentially suspect part
	Recall compo	onent differen Illover sensor	, the production range of po nce to non-recall componen r which may not have been p	t: The air bag control unit
Production Dates : VIN Range 1 :		0 - MAR 20, 2 NR	2020 End: NR	☐ Not sequential

20V-283

Vehicle Type :	2021-2021 MINI Hardtop LIGHT VEHICLES	2 Door (Cooper S E)	
Body Style : Power Train :	2-DOOR HYBRID ELECTRIC		
	Approximately 8 vehicles	are equipped with an air bag 7 not have been produced to	
	records were reviewed to		embly and supplier production nge of potentially suspect part entially affected vehicles.
		ce to non-recall component: which may not have been pr	
Production Dates :	MAR 18, 2020 - MAR 18, 2	020	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential
Vehicle Type : Body Style : Power Train :	GAS	VEHICLES	a
Descriptive Information :		s are equipped with an air ba 7 not have been produced to	
	records were reviewed to		mbly and supplier production nge of potentially suspect part entially affected vehicles.
		ce to non-recall component: which may not have been pr	
	MAR 12, 2020 - MAR 20, 2		
	Begin : NR	End: NR	□ Not sequential

20V-283

Vohielo 6	2020-2020 MINI Clubman (Cooper S All4)	
	LIGHT VEHICLES	
Body Style :		
Power Train :		
	Approximately 1 vehicle is equipped with an air bag control unit cont sensor which may not have been produced to supplier specifications.	aining a rollover
	Basis for recall population determination: Vehicle assembly and supprecords were reviewed to determine the production range of potentia and, via parts traceability, the production range of potentially affected	ally suspect parts
	Recall component difference to non-recall component: The air bag co contains a rollover sensor which may not have been produced to sup specifications.	
Production Dates : VIN Range 1 : F	MAR 19, 2020 - MAR 19, 2020 Gegin : NR End : NR	Not sequential
		<b>1</b>
-		
-	t : This safety recall involves the rollover sensor within the air bag co which may not have been produced to supplier specifications. Du production, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a re	ontrol unit ring supplier d with an bonding pad
-	t : This safety recall involves the rollover sensor within the air bag co which may not have been produced to supplier specifications. Du production, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a re- not be possible for the sensor to detect a rollover condition.	ontrol unit ring supplier d with an bonding pad
-	<ul> <li>t: This safety recall involves the rollover sensor within the air bag constrained which may not have been produced to supplier specifications. Duproduction, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a renot be possible for the sensor to detect a rollover condition.</li> <li>1: NR</li> </ul>	ontrol unit ring supplier d with an bonding pad
Description of the Defeo FMVSS FMVSS	<ul> <li>t: This safety recall involves the rollover sensor within the air bag constrained which may not have been produced to supplier specifications. Duproduction, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a renot be possible for the sensor to detect a rollover condition.</li> <li>1: NR</li> </ul>	ontrol unit ring supplier d with an bonding pad sult, it may
Description of the Defeo FMVSS FMVSS	<ul> <li>t: This safety recall involves the rollover sensor within the air bag converses which may not have been produced to supplier specifications. Duproduction, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a renot be possible for the sensor to detect a rollover condition.</li> <li>1: NR</li> <li>2: NR</li> <li>3: In a crash involving a rollover, deployment of the head air bag and pretensioner, and activation of other safety systems, may not occur could increase the risk of injury.</li> </ul>	ontrol unit ring supplier d with an bonding pad sult, it may
Description of the Defect FMVSS FMVSS Description of the Safety Ris Description of the Caus Identification of Any Warni	<ul> <li>t: This safety recall involves the rollover sensor within the air bag converses which may not have been produced to supplier specifications. Duproduction, an oxide etching machine may have been programme incorrect parameter. If this occurred, then the sensor's aluminum may delaminate from a poly layer substrate on the sensor. As a renot be possible for the sensor to detect a rollover condition.</li> <li>1: NR</li> <li>2: NR</li> <li>3: In a crash involving a rollover, deployment of the head air bag and pretensioner, and activation of other safety systems, may not occur could increase the risk of injury.</li> </ul>	ontrol unit ring supplier d with an bonding pad esult, it may I safety belt ır, which

The information contained in this report was submitted pursuant to 49 CFR §573

Component Name 1 : ACSM4i, Mid-Roll Component Description : Air Bag Control Unit Component Part Number : 9873244-01

### **Supplier Identification :**

### **Component Manufacturer**

Name :ZF Automotive Germany GmbHAddress :Fritz-Reichle-Ring 8<br/>Radolfzell FOREIGN STATES 78315Country :Germany

#### Chronology :

On March 19, 2020, the air bag control unit supplier informed BMW that certain control units may have been produced with rollover sensors that do not meet specifications.

Between April and May, an engineering analysis, and a review of the supply chain was conducted. A review of supplier quality control records revealed that during a training session, an oxide etching machine may have been programmed with an incorrect parameter. Further reviews suggested that this could cause the rollover sensor to be produced with an inadequate or uneven amount of etching.

This could allow the sensor's aluminum bonding pad to delaminate from a poly layer substrate on the sensor. An analysis indicated that a reduced robustness of the sensor could occur which could lead to a premature failure of the air bag control unit during vehicle operation and its ability to detect a rollover condition. An examination of supplier quality testing indicated that even with the potential for an etching anomaly, the sensors passed all functional testing.

Vehicle assembly information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.

On May 13, 2020, BMW Group decided to conduct a voluntary recall for potentially affected vehicles.

BMW Group has not received any reports, nor is BMW Group otherwise aware, of any accidents or injuries related to this issue.

20V-283

20V-283

Page 6

## **Description of Remedy :**

	Description of Remedy Program :	The air bag control unit will be replaced.
		If this condition were to occur to a potentially affected vehicle prior to the recall, the remedy would be covered by the BMW and MINI New Vehicle Limited Warranty program. Therefore, reimbursement for a prenotification remedy re Part 573.13 and Part 577.11 is not necessary.
	How Remedy Component Differs from Recalled Component :	Recalled Component: air bag control unit (ACSM4i, Mid-Roll); p/n (9873244-01).
]	dentify How/When Recall Condition was Corrected in Production :	NR

### **Recall Schedule :**

Description of Recall Schedule :	Notification to dealers is planned to begin and end on May 20, 2020. Notification to owners is planned to begin and end on July 13, 2020.
Planned Dealer Notification Date :	
Planned Owner Notification Date :	JUL 13, 2020 - JUL 13, 2020

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573