OMB Control No.: 2127-0004

Recall Quarterly Report

20V-678

Manufacturer Name: BMW of North America, LLC **NHTSA Recall No.** / **MFR Recall No.**: 20V-678 /

Recall Subject: Front Axle/Right Control Arm Not Welded Properly

Owner Notification Beginning Date : DEC 18, 2020

Owner Notification End Date: DEC 18, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 30, 2021	2021-2	83	82	0	0
2	APR 30, 2021	2021-1	83	81	0	0
1	JAN 26, 2021	2020-4	83	73	0	0

This Document Last Updated: AUG 03, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.