

**Recall Quarterly Report****20V-678****Manufacturer Name :** BMW of North America, LLC**NHTSA Recall No. / MFR Recall No. :** 20V-678 /**Recall Subject :** Front Axle/Right Control Arm Not Welded Properly**Owner Notification Beginning Date :** DEC 18, 2020**Owner Notification End Date:** DEC 18, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 25, 2021	2021-3	83	83	0	0
3	JUL 30, 2021	2021-2	83	82	0	0
2	APR 30, 2021	2021-1	83	81	0	0
1	JAN 26, 2021	2020-4	83	73	0	0

This Document Last Updated : OCT 26, 2021

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.